

EPA Notification of Hazardous Waste Site

U.S. Environmental Protection Agency
Washington, DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies

EPA Region 5 Records Ctr.



387744

910609

MN #148

MNS-000-001-141

Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name NA

Street NA

City NA

State

Zip Code

Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Kitzville Dump (Old Hibbing Dump)

Street

T57, R20, S3, SW1/4 NW1/4 ML S. HWY 92 1/2 MI. E. 169

City Hibbing

County

St. Louis State MN

Zip Code 55764

MND980609754

Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Kurtz, James, Supervising Sanitarian

Phone

(218) 727-8068

Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) Unknown

To (Year) 6/22/78

1978

Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item 1—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Organics
2. ☐ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☒ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

1. ☐ Mining
2. ☒ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☒ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

000001 JUL -981

JUL 9 1981

Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

Cubic feet: Unknown

Gallons: Unknown

Total Facility Area

square feet: Unknown

acres: Unknown

Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☒ Suspected ☐ Likely ☐ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name _____

Street _____

City _____

State _____

Zip Code _____

Signature _____

Date _____

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☒ Other

St. Louis County

HEALTH DEPARTMENT

EXECUTIVE OFFICER,
HAROLD B. LEPPINK, M.D., M.P.H.

504 East Second Street • Duluth, Minn. 55805
Telephone 727-8661

July 1, 1981


Director
Office of Superfund
Sites Notification
US EPA Region 5
Chicago, IL 60604

RE: HIBBING SERVICE AREA LANDFILL AND KITZVILLE DUMP (OLD HIBBING DUMP), COUNTY OF ST. LOUIS, STATE OF MINNESOTA

On June 29, 1981 I discussed with Bruce Mibeck, EPA-Chicago, the necessity to complete the EPA notification of hazardous waste site forms. The conclusion of the discussion was that the County of St. Louis is not required to notify the EPA of possible hazardous waste sites. However, we are enclosing the report forms for the Hibbing Service Area Landfill and the Kitzville Dump (Old Hibbing Dump).

Additional information on these sites was obtained in 1980 through an EPA investigation initiated by employees of Irathane Systems, Inc. of Hibbing. Analysis of samples for MOCA, by EPA, indicated very low parts per billion.

If we may be of further assistance, please feel free to call on us.



James Kurtz
Supervising Sanitarian

Enc.

JK/bd

JUL 09 1981

America's Iron Ore Center...



at the Head of the Seaway

"An Equal Opportunity Employer"

HEALTH DEPARTMENT
ST. LOUIS COUNTY
504 EAST SECOND STREET
DULUTH, MINNESOTA 55805



US EPA Region 5
Sites Notification
Chicago, IL 60604